

## TECHNICAL REPORT





Object: HB 3600 DP - s/n DEQ181132 ( y 2018 )

## **Status:**

Used actually in our Dealer Workshop dismantled and complete in each part.

Main **Components\*** parts are good working order **standard and original**.

Only **PIston is missing** and can be provided on customer request ORIGINAL or AFTERMARKETS Top Quality by OMD in Italy ( *www.demolitioriomd.com* )

\*top head, cylinder, front head and also Tie-Rods are all ok and genuine.

More photos can be provided if interested.

**SOLD AS IS NO WARRANTY or FULLY REBUILD with 6 Months Warranty** 

Pasquale Depalo 29/08/2025 +39 335 75 74 116 info@repalo.it